


6.3 - EXTENSION FOR INSTALLATION ON DENTAL UNIT

In dental units that mount lamps with arched arm, the rest position of the head of the Esa-line lamps, once replaced, is too low. This is due to a different design of the pantograph arms. In this case it is suggested to consider the optional 15 cm extension with dimensions and codes available as in the figure:

STANDARD EXTENSION



COMPOUND EXTENSION

